



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)
T.R. PATTINAM - 609606, KARAİKAL.



Phone No: 04368- 233060,

E-Mail: ppclmmc@gmail.com

Ref. No: AC-104/MMC/2025-26/ **1531**

Dt. **27**.11.2025

Our GSTIN No.: 34AAACP6507E1ZS

ENQUIRY

To

Sub: Inviting offer for Gas turbine Intake Air Filter Duct Minor Repair Work and Filter Elements Replacement Work at PPCL, T.R.Pattinam, Karaikal - Reg.

QUOTATION TO BE:

Submitted on or before 18.12.2025- 12.00 PM	Opened on 19.12.2025 -03.00PM
Kept valid up to three months	Submitted in ONE PART.

Wax Sealed quotations are invited for Gas turbine Air Intake System-Bottom Portion Repair Work at PPCL, T.R.Pattinam, as per the scope of work furnished in the annexure and as per our terms and conditions mentioned therein.

PRE-QUALIFICATION REQUIREMENTS:

The bidder shall have proven experiences in the field of structural/pipeline fabrication work at Power houses or Industries. In proof of the above, work order copies / work completion certificates/ work order copies with invoices within last seven years should be furnished.

TERMS AND CONDITIONS:

1. The rate quoted should be inclusive of manpower, tools and tackles, etc. required for the works, **all taxes, EPF & ESI charges and other charges** as admissible. **GST Compliance will be made as per the latest GOI orders.**
2. 100% Payment will be made within 30 days from the date of receipt of your invoice after completion of work satisfactorily and approval of Engineer-in-charge and after submission of EPF/ESI, etc. documents. Otherwise 80% payment will be made after completion of work satisfactorily and approval of Engineer-in-charge and the balance 20% payment will be made after submission of necessary EPF & ESI, etc. documents.
3. The bill in triplicate along with advance stamped receipt should be sent to the undersigned for effecting payment.
4. **Rate should be quoted per work in the tabular column attached. The L1 position shall be arrived on total amount quoted basis for completing the entire scope of work furnished in the annexure.**
5. The Contractor / Agency awarded with work order shall make payments for ESI & EPF in separate code number other than PPCL code. No permission shall be given for PPCL code.



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)
T.R. PATTINAM - 609606, KARAIKAL.



Phone No: 04368- 233060,

E-Mail:ppclmmc@gmail.com

Ref. No: AC-104/MMC/2025-26/ **1531**

Dt. **27** .11.2025

Our GSTIN No.: 34AAACP6507E1ZS

ENQUIRY PAGE NO. 2

6. The contractor should submit the following:

For EPF:

To be generated from the EPF website for the specific month for the manpower deployed to PPCL and the same to be enclosed separately with a covering letter.

- i) Combined challan of account no. 01,02,10,21 & 22 with TRRN number.
- ii) EPF - Electronic Challan cum Return (ECR)
- iii) EPF Clallan summery/ EPF - TRRN details

For ESI:

To be generated from the ESI website for the specific month for the manpower deployed to PPCL and the same to be enclosed separately with a covering letter.

- i) ESI challan number
- ii) ESI monthly contribution- online challan status (Transaction details)
- iii) ESI monthly contribution details (contractor wise) for the month of.....

And other records to be submitted along with the above:

Copy of register of wages for the persons deployed to PPCL duly attested by the contractor.

Copy of register of muster roll/attendance for the persons deployed to PPCL duly attested by the contractor.

Copy of payment proof for the persons deployed to PPCL through bank duly attested by the contractor.

In addition to the above as a mandatory, the proposed parties/manpower supply contractors have to obtain the FORM-III -Registration certificate under Pondicherry shops and Establishment Rules 1964 as a Employer of the Establishment to be permitted to employ persons under their firm and also obtain Labour License under the contract labour (Regulation & Abolition act. 1970 with the labour Department, Government of Puducherry, Karaikal.

7. Necessary Gate pass should be obtained well before the commencement of work.
8. All the Safety Rules as per the Factory Act 1948, Puducherry Factory Rule and PPCL Safety instructions to be strictly followed inside the plant area.
9. In case of any faulty workmanship in the scope of work, the tenderer must rectify the same. Otherwise the estimated amount will be deducted in work bill.
10. Our GSTIN No.: 34AAACP6507E1ZS registered with Commercial Taxes Department, Puducherry.



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)

T.R. PATTINAM - 609606, KARAIKAL.



Phone No: 04368- 233060,

E-Mail:ppclmmc@gmail.com

Ref. No: AC-104/MMC/2025-26/1531

Dt. 27.11.2025

Our GSTIN No.: 34AAACP6507E1ZS

ENQUIRY PAGE NO. 3

11. The bidder should provide pre-existing document for PQR copies as and when asked within one week time.
12. Sealed quotation should be super scribed as "AC-104- Gas turbine Intake Air Filter Duct Minor Repair Work and Filter Elements Replacement Work "at PPCL, T.R.Pattinam, Karaikal - due on 18.12.2025.
13. Applicable other charges, if any should be clearly mentioned as whether inclusive or exclusive. If not mentioned, it will be presumed that the rate quoted is inclusive of all taxes other charges.
14. The party should submit two copies of photographs of all the employees deployed in PPCL for the above work for gate pass purpose. The name & photo of the employees should be attested by the contractor.
15. The undersigned reserves all rights to accept/reject any or all the quotations without assigning any reasons thereof.
17. The work should be completed within five days from the commencement of shutdown.
18. Pre-fabrication works may be taken before plant shutdown minimum five days shall be given for mobilization. The date of work commencement shall be communicated separately.
19. The work should not be sub-let. Sub-contracting not permitted.

EXECUTIVE ENGINEER (MECH)-PLANT



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)

T.R. PATTINAM - 609606, KARAIKAL.



Phone No: 04368- 233060,

E-Mail: ppclmmc@gmail.com

Ref. No: AC-104/MMC/2025-26/ 1531

Dt. 27.11.2025

Our GSTIN No.: 34AAACP6507E1ZS

Annexure-1

**SCOPE OF WORK FOR GAS TURBINE INTAKE AIR FILTER DUCT MINOR REPAIR WORK
AND FILTER ELEMENT REPLACEMENT WORK**

1. Provide Scaffoldings on both deck of Gas Turbine air filtration system. (Approx area 550 square feet x 2 decks at 4 meter and 6 meter level)
2. Remove the old filters element- 360 numbers from the duct system.
3. Clean out side & inside of the ducts.
4. Inspect filter clamp bracket, clamp bar, formed channel, handles and the filter fixing seat portion for any corrosion/damage.
5. Dismantle the Old corroded sheets, interconnecting ducts, support formed channel, clamp bracket and eductor tubes and inlet duct corroded portion etc., from the existing location as indentified Engineer in-charge.
6. If any damages/corrosion noticed or identified in above clamp bracket, clamp bar, formed channel etc, are to be replaced/ repair by the contractor as per the existing dimension. Material will be supplied by PPCL.
7. Duct inside/outside to be inspected, wherever corrosion noticed to be patch welded. Approximate area of batch welding is 100 square feet.
8. Welding, testing, Inspection of external side should be as per the scope of work.
9. Shifting and Fixing of new filter elements (360 Nos.) and locking the clamps.
10. All connected structures, piping and fittings related to Gas turbine intake air filter system are to be reconnected as per the existing system.

Contractor's Obligations:

1. Before submitting the offer, party must visit the site PPCL, Karaikal, to have correct assessment of the job.
2. All safety rules as per the Factory Act 1948, Puducherry Factory Rule and PPCL Safety Instructions should be strictly followed inside the plant area.



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)
T.R. PATTINAM - 609606, KARAIKAL.



Phone No: 04368- 233060,

E-Mail:ppclmmc@gmail.com

Ref. No: AC-104/MMC/2025-26/ 1531

Dt. 27 .11.2025

Our GSTIN No.: 34AAACP6507E1ZS

3. The contractor shall provide necessary PPE's (Safety Helmet, Goggles, and Gloves, Safety shoes, etc.,) for all the employees who are engaged in the work.
4. Contractor must have past experience, infrastructure and trained manpower in fabrication of MS structural of any industry. Relevant documentary evidence should be attached.
5. Party shall make their own arrangements for Welding sets, Gas Cutting Sets, Lifting equipments, Tools and Tackles, scaffolding materials and Other Rigging Material required for completing the job.
6. All consumables like Oxygen Gas, Acetylene Gas, Argon Gas Cylinders, and Welding Electrodes, etc., shall be arranged by the party.
7. If any additional structures, equipments, piping are required to be removed, to facilitate the erection, the same will be in party's scope, without any extra charges. All the structure, after completion of job, shall be installed back to its original position by the contractor without any extra charges.
8. If any damage or loss caused to Plant Equipment, etc., during execution of this contract that will be made good by the contractor at his own cost and risk.

PPCL Obligations:

1. Electrical Power and Water shall be provided at free of cost.
3. Raw Material (flat & pipe) will be provided by PPCL.



PUDUCHERRY POWER CORPORATION LIMITED
(A GOVERNMENT OF PUDUCHERRY UNDERTAKING)
T.R. PATTINAM - 609606, KARAİKAL.



Phone No: 04368- 233060,

E-Mail:ppclmmc@gmail.com

Ref. No: AC-104/MMC/2025-26/1531

Dt. 21.11.2025

Our GSTIN No.: 34AAACP6507E1ZS

ANNEXURE Page-2

Name Of Work: "GAS TURBINE INTAKE FILTER DUCT MINOR REPAIR WORK AND FILTER ELEMENTS REPLACEMENT WORK" at PPCL, T.R.Pattinam, Karaikal.

Note: Scope of work for Gas turbine Intake filter duct minor repair work and filter elements replacement work is as per the enquiry annexure -1

Sl. No	Specification	Amount in RS.
1.	Gas turbine Intake Air Filter Duct Minor Repair Work and Filter Elements Replacement Work at PPCL as per the scope work mentioned in the enquiry annexure - I	
	Material cost, labour charges, safety material, consumables, scaffolding charges, tools & tackles and other inputs	Inclusive
	Transport, Accommodation, Boarding and EPF & ESI Charges	Inclusive
	Sub Total	
	GST @ 18%	
	Grand Total	
Total Rs. in words:		

Sl.No	Details	Terms in Enquiry	Terms Accepted by the Party
1.	Price Quoted	Inclusive of Material cost, labour charges, safety material, consumables, scaffolding charges, tools & tackles, ESI & EPF and other charges as per the scope of work in Annexure- I all taxes and charges admissible	
2.	Payment Terms	As per Clause 2 of the General terms and conditions of our enquiry	
3.	Validity	90 Days from the date of opening	
4.	Scope of work	As per Annexure - I	
5.	Acceptance of all our terms & conditions of our Enquiry	To be accepted	

Note: 1) The rates to be quoted in all the columns of the above schedule and no columns should be left blank, if any column is left blank then the offered quotation will not be considered.

2) The quoted schedule should be affixed by the company seal and signed by the concerned authority.

Name of the Company:

Company seal with Signature: